

NOTICE GANGGUAN BEKALAN ELEKTRIK
NOTICE OF SUPPLY INTERRUPTION
停电通告

Pelanggan yang dihormati,

Adalah dimaklumkan bahawa kawasan anda akan mengalami gangguan bekalan elektrik pada hari dan waktu seperti yang dinyatakan di bawah bagi membolehkan kerja-kerja penyelenggaraan dijalankan.

Sekiranya keadaan cuaca tidak mengizinkan kerja-kerja tersebut dijalankan, notis gangguan bekalan elektrik ini akan ditangguhkan pada masa yang akan dimaklumkan kemudian.

Pihak kami akan berusaha untuk memulih bekalan elektrik di kawasan anda dengan secepat mungkin. Kesulitan yang timbul amatlah dikesali.

Terima kasih.

Dear valued customer,

Please be informed that there will be power interruption in your area on the date and time mentioned below. The interruption is to enable our technical teams to carry out maintenance and upgrading work on the distribution system.

However, if the weather does not permit the work to be carried out, this planned shutdown will be postponed until further notice.

We regret for the inconveniences caused and will make efforts to restore the electricity supply within the shortest possible time.

Thank you.

敬愛的用戶，

砂拉越電力公司將於以下日期及時間進行維修與提升工作，因此，貴區電流供應將受影響。倘若天氣不適，維修工作將展延，時間及地點將另行通知。

砂拉越電力公司將盡全力在最短時間內恢復電流供應。不便之處，敬請見諒。

謝謝。

Tarikh/Date/日期	Masa Penutupan/Shut Down Time/ 停电时间	Masa Penyambungan/Time Restore/ 恢复时间
04-07-2026	09:00:00	14:00:00

Areas Affected: All consumer at Skuau Resettlement Scheme

Oya.

Scope of work: Low voltage cluster at Rh Seti Sg Segu Sekuau
[CRM1860836-26]

1. To install 2 nos LT OHL pole after pole SRS34/20 Sacofa Sekuau [DS30886] Sub
2. Disconnect jumper LT OHL 7/122 at Belian poles in front Rumah Panjang Rh Seti Sg Segu Sekuau
3. To install new pole mounted fuse at SRS34/5 SK Penghulu Imban Sub [DS35563]
4. To erect 7 spans LV aerial cable from Sacofa Sekuau Sub to LT OHL pole Rh Seti Sg Segu Sekuau

5. To lay 70mm² cu cables from LT pole mounted fuse to LT OHL at SRS34/5 Sk Penghulu Imban Sub. [DS35563]
6. To convert intermediate pole to Section pole at Sk Penghulu Imban Sub
7. To clear potential danger tree near to 11kV OHL from pole SRS10 - SRS43 Jalan Skuau (OHL Team)

Pertanyaan Lanjut/Further Enquiries/询问:

Pusat Khidmat Pelanggan/Customer Careline/客户服务中心

1300-88-3111

Ref:

Project Officer: Wan Hafizuddin Azri Wan Bujang


Leonard Lai
Senior Manager
Operation & Maintenance
Syarikat SESCO Berhad, Sibu

b/p Pengurus Wilayah (Tengah)

for Regional Manager (Central)

区域经理 (中区)

Syarikat SESCO Berhad 200401034422 (672931-A)

A Subsidiary of Sarawak Energy Berhad